ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	11	Kuvempu Nagar
Street ID	**Street Name**	**Significant Landmark**
W0218, W0335, W0347, W0027, W0349, W0333, W0214, W	NA, R H B Colcny 2nd Main Rd, 7th Main Rd, G M Palya, Chikka Muniswammappa Lyt, 2nd Crs, 11th Crs La	Singapura
Segment No.	**Total Length (m)**	
11/C-W0218/S010100	585.64	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	33.12	77.538493	13.078789	77.538796	13.078754	W0027	DEAD END
2	38.80	77.538724	13.079026	77.538767	13.079375	W0232	DEAD END
3	14.75	77.538526	13.079195	77.538545	13.079327	W0027	DEAD END
4	62.29	77.538080	13.078907	77.538266	13.079440	W0230	W0027
5	94.62	77.537531	13.078958	77.538394	13.078833	W0351	W0027
6	34.80	77.537553	13.079470	77.537520	13.079157	W0335	W0224
7	72.77	77.537271	13.079561	77.537928	13.079427	W0333	W0351
8	64.18	77.537758	13.080099	77.537592	13.079543	W0027	W0335
9	80.50	77.537327	13.079579	77.537466	13.080292	W0319	W0335
10	45.50	77.536908	13.079806	77.537302	13.079664	DEAD END	W0333
11	44.31	77.536798	13.079652	77.537183	13.079516	DEAD END	W0335

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Road and Drains at Singapura in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	4000000	2015
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Improvements to Road and Drains at Singapura in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	011-16-000005
Work Order No.	**Work Order Date**	**Period of Extention**
	24/03/2016	90 DAYS

EE/BTP/BBMP/E-PMT/322/2015-16

Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
24/03/2016	23/03/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
ASHWATHNARAYA		0.00
Phone No.	**E-Mail ID**	
9448034435		

Field Inspection Details

Number of Trees	Any Other Information	Name
5		SURESH
Date of Inspection	**Remarks**	
27/06/2016	completed	

Category	Image	Photo Remark
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.

Zone: YELAHANKA **Ward No:** 11 **Ward Name:** Kuvempu Nagar **Street ID:** W0218, W0335, W0347, W0027,

Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	27/06/2016	27/07/2016	COMPLETED
SE	VASU K M	27/06/2016	27/07/2016	COMPLETED
EE	YARAPPA REDDY	27/06/2016	27/07/2016	COMPLETED
AEE	SHIVAKUMAR	27/06/2016	27/07/2016	COMPLETED
AE	SURESH	27/06/2016	27/07/2016	COMPLETED
AE	SURESH	27/06/2016	27/07/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 11 **Ward Name:** Kuvempu Nagar **Street ID:** W0218, W0335, W0347, W0027,